

AR COATING CARE

Anti-reflective (AR) coating is a clear, delicate layer on your lenses that reduces glare. Because it can scratch, peel, or crack easily, it needs extra gentle care to stay crystal clear.



5 EASY STEPS

1



RINSE FIRST

Wash away dust before wiping.

2



USE GENTLE CLEANER

Spray with lens cleaner or mild dish soap.

3



MICROFIBRE ONLY

No tissue, towels or shirts & t-shirts.

4



STORE SAFELY

Keep in hard case when not in use.

5



KEEP COOL

Avoid heat, steam and hot cars.